

TECHNICAL BULLETIN

No: LTB00328 (ISSUE 1)
18 JANUARY 2011

RANGE ROVER



CIRCULATE TO: SERVICE PARTS WARRANTY BODY SHOP
 ✓ ✓ ✓ ✓

SECTION: 501

Rear Door Window Regulator - Lower Level Service Repair

AFFECTED VEHICLE RANGE:

LR3 (LA)

VIN: 5A000360 - 9A513325

Model Year: 2005 - 2009

Range Rover Sport (LS)

VIN: 6A900290 - 7A999999

7A100000 - 9A212143

Model Year: 2006 - 2009

CONDITION SUMMARY:

Situation: A lower level rear door window regulator service repair is now available if a rear door window(s) is inoperative or operating slowly.

Action: In the event of a customer concern of the above, refer to the Repair Procedure outlined below to inspect and, if necessary, replace the rear door window motor only.

PARTS:


CVR000010.....Motor - RH Qty: 1

CVR000060.....Motor - LR Qty: 1

TOOLS:

Refer to Workshop Manual for any required special tools

WARRANTY:

 **NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.**

DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Range Rover Sport - Motor Rear Door Renew	86.25.09	0.70	42	CUH500103
Discovery 3/LR3 - Motor Rear Door Renew	86.25.09	0.80		
Check The Motor functionality And Harness	05.10.10	0.10		

Normal Warranty policies and procedures apply

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

REPAIR PROCEDURE

CHECK REAR DOOR WINDOW MOTOR FUNCTIONALITY AND HARNESS



CAUTION: Do not cut the rear window regulator drive cable during any part of this Repair Procedure.

1. Refer to Workshop Manual, section 501-05, and remove the rear door trim panel.
2. Remove the rear window motor electrical connector.
3. Apply an independent 12v and ground feed onto the motor buzz bars: (Figure 1)
 - Ensure the feeds are reversed to enable the glass to move both up and down.
 - If normal window movement is evident, continue to step 4
 - If NO movement is evident, continue to REPLACE REAR DOOR WINDOW MOTOR.
4. Check the harness electrical connector for damage.
 - Repair and or replace electrical connector if applicable.
5. Check the harness connector for electrical feed.
 - Resolve the electrical feed if applicable.
6. Check the position of the motor buzz bars: (Figure 2)
 - If one of the buzz bars is pushed back, continue to REPLACE REAR DOOR WINDOW MOTOR.

Figure 1






Figure 2



REPLACE REAR DOOR WINDOW MOTOR

 **CAUTION:** Do not cut the rear window regulator drive cable during any part of this Repair Procedure.

1. Remove the three screws. (Figure 3)

 **NOTE:** Following this step will disengage the motor from the drum, allowing the window to lower.

2. Release the window motor by pulling it upwards towards the trim support bracket, releasing the rear window motor from the drum. (Figure 4)
3. Refer to Workshop Manual, section 501-11, and remove the window regulator.

4. Remove the trim supporting bracket: (Figure 5)
 - Remove the three screws.
5. Remove the rear window regulator motor.
6. Install the new window regulator motor: (Figure 3)
 - Install the three screws.
7. Install the trim supporting bracket: (Figure 5)
 - Install the three screws.
8. Refer to Workshop Manual, section 501-11, and install the window regulator.
9. Verify window operation.

Figure 3



Figure 4




Figure 5

