

TECHNICAL BULLETIN
LTB00479v2
14 AUG 2012



© Jaguar Land Rover Limited
All rights reserved.

This reissue replaces all previous versions. Please destroy all previous versions. Only refer to the electronic version of this TSB in TOPIX.
This bulletin supersedes TSB LTB00479/2012 dated 07 AUG 2012, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this TSB in TOPIX.

SECTION: 309-00

3.0L TDV6 Exhaust Weld

AFFECTED VEHICLE RANGE:

Discovery 4 / LR4 (LA)	Model Year:	2010-2012
	VIN:	AA510178-CA638508
Range Rover Sport (LS)	Model Year:	2010-2012
	VIN:	AA212145-CA771688

MARKETS:

All Diesel Markets

CONDITION SUMMARY:

Situation:

This bulletin is for information only.

This version has been issued for a change to the Summary.



NOTE: The one piece exhaust is production fit only. For service repairs where the weld has broken prior to the cut off VIN numbers please refer to TOPIX Workshop Manual, section 309-00 Exhaust System for repair guidance.

A new (weld less) one piece exhaust system has now been introduced from Production from the following VIN numbers – Discovery 4 – CA638508 Range Rover Sport – CA771688

If appropriate a local repair of the weld can be claimed under a ZZZ001 warranty claim.

Cause: Poor weld during manufacturing of the exhaust at the supplier.