File Edit View History Bookmarks Tools Help

DSG5/LEON - Mk5 is b... × file:///C:/Drive Allergy/Jim/Customers_Files/SEGA/SCC/CMOS/MiniPatch-107

file:///C:/Drive Allergy/Jim/Customers_Files/SEGA/SCC/CMOS/MiniPatch-107

current is clue

Gnome - BBC Sport Facebook | Mods Condo... DSG5/CLEON - Swards Sign In MOBA[CloudGAME] |... BRIGHTSTAR + Index My Surgery Website B... http://www.youtube.c... Photoshop Yahoo! Advanced Factors For ...

Micro Dips wheel Buttons Selected	Inactive [47.39%]
Heated Steering Wheel	Not Fitted [100%]
ATR Gritss/Gravel/Snow Mode Resets After Time	No [100%]
Clock Display Format	24 Hour clock [95.98%]
Adjustable Pedal Box	Inactive [100%]

Infotainment

Integrated Head Unit Low Line	Fitted [27.58%]
Integrated Head Unit AM / FM Tuner	Not fitted [27.58%]
Integrated Head Unit Internal Audio Player Module Type	Integrated audio module not fitted [100%]
Integrated Head Unit Internal CD	Not fitted [27.58%]
Integrated Head Unit Internal DVD	Not fitted [100%]
Integrated Head Unit Internal Mainline	Not fitted [100%]
Integrated Head Unit In Band On Channel Receiver	Not fitted [100%]
Integrated Head Unit Faceplate	Integral faceplate fitted [100%]
Integrated Head Unit Error	No [100%]
Integrated Head Unit Reserved	Parameter not used. [100%]
High Level Display Front (HLDF) Fitment	Not fitted with high level display front (touchscreen), [52.39%]
Multi Media Module (HLDF) Country	Multi-media module is not fitted, [52.39%]
Multi Media Module (HLDF) DVD Mechanism	Horizontal DVD mechanism,
Multi Media Module (HLDF) Fromtor Level (eg 4x4 Info)	Undefined [52.33%]
Multi Media Module (HLDF) Fitment	Multi-media module is not fitted, [52.33%]
Multi Media Module (HLDF) Input Spec	Undefined [52.33%]
Multi Media Module (HLDF) Manufacturer Mode	DENSO mode [52.96%]
HLDF Main Menu	Disabled [100%]
Rear Seat Entertainment Interface Module Fitment	Interface module not fitted [99.15%]
Rear Seat Entertainment DVD Player Fitment	DVD player is not fitted [99.15%]
Rear Seat Entertainment DVD Audio Configuration	Not DVI audio compatible. [100%]
Rear Screen Fitment	Yes [99.15%]
Rear Seat Entertainment Right Head Display Fitment	Not fitted [99.15%]
Rear Seat Entertainment Left Head Display Fitment	Not fitted [99.15%]
Rear Seat Entertainment Additional Display 3	Not fitted [100%]
Rear Seat Entertainment Additional Display 4	Not fitted [100%]
Rear Seat Entertainment Additional Display 5	Not fitted [100%]
Rear Seat Entertainment Error	No [100%]
Rear Seat Entertainment Reserved	Not fitted [100%]
Headphone Sockets Fitment	No rear headset socket fitted. [72.53%]
Headphone Socket 1 is Fitted	Not fitted [72.53%]
Headphone Socket 2 is Fitted	Not fitted [72.53%]
Headphone Socket 3 is Fitted	Not fitted [75.21%]
Headphone Socket 4 is Fitted	Not fitted [75.21%]
Audio Visual Fitment	Audio visual (not fitted) 99.15%]
Audio Visual Audio Input	Not fitted [99.15%]
Audio Visual Audio Ouput	Not fitted [100%]
Audio Visual AutoKey Input	Not installed [27.58%]
Audio Visual ISO13M (Firewire)	No [100%]
Audio Visual USB 1	No [100%]
Audio Visual USB 2	Not fitted [100%]
Audio Visual Video Input	Not fitted [99.15%]
Audio Visual Video Output	Not fitted [100%]
Front AutoKey	Disabled [100%]
Television Type	Television not fitted [92.34%]
Television Receiver type	Receiver not fitted. [92.34%]
Ventura / Companion Camera Docking Station	Companion not fitted. [100%]
Ventura / Companion: Camera 1	Not fitted [100%]
Ventura / Companion: Camera 2	Not fitted [100%]
Ventura / Companion: Camera 3	Not fitted [100%]
Ventura / Companion: Camera 4	Not fitted [100%]
Ventura / Companion: Camera 5	Not fitted [100%]
Companion Camera Signaller Test Mode	No [100%]
Ventura / Companion Camera Frequency	Companion frequency 432. [100%]
Ventura / Companion: Cam Disable Speed	Undefined [100%]
Companion Cam Error	No [100%]
Parking Camera Fitment	No parking camera fitted [100%]
Bluetooth	Bluetooth enabled [95.20%]
Accessory Phone	Disabled [100%]
Cellular Telephone	Cellular Adaptronic not fitted [60%]
Short Message Service (SMS Read Last)	Enabled while driving [75.27%]
Microphone	Not fitted with a microphone. [92.20%]
Cellular Telephone Voice Language	UK English [98.46%]
Speech Control Language	0
Voice Control	Not fitted [92.20%]
Text to Speech Language	0
Asclip Amplifier Type Fitted	Amplifier is not fitted. [27.58%]
Centre Speaker	Undefined [100%]
Subwoofer	No subwoofer fitted. [27.58%]
Diversity Antennas Fitment	Diversity antennas not fitted. [27.58%]
Asclip Systems Country / Region Configuration	Europe (77.53%)
AM / FM	Disabled [100%]
CD Unit Type	Single slot CD player [27.58%]
MiniDisc	A ramdisc is not fitted. [100%]
Entertainment System Bus Type	Medium speed CAN based system fitted. [27.58%]
Entertainment Package	Undefined [100%]
Region for Low Line Infotainment	Europe [100%]
CD player Type	Single CD mechanism is fitted. [27.58%]
Entertainment Reserved 1	Parameter not used. [100%]
Entertainment Reserved 2	Parameter not used. [100%]
Entertainment Reserved 3	Parameter not used. [100%]
Media Player 1	Parameter not used. [100%]
Media Player 2	Parameter not used. [100%]
Media Player 3	Parameter not used. [100%]
Media Player 4	Parameter not used. [100%]
Mobile Office	Not fitted with mobile office. [100%]
My Connected World	Parameter not used. [100%]
Intercom Fitment	Fitted with intercom. [94.24%]
Intercom	Parameter not used. [100%]
Global Positioning System (GPS) Receiver Type	Global positioning system not fitted. [52.39%]
Navigation System Fitment	Not fitted with navigation. [52.39%]
Navigation System Region	Europe (80.50%)
Mode for Navigation Interface (Navi on Meter)	Disabled [99.05%]
Customer Personalisation Fitment	Not fitted [25.19%]
Customer Personalisation Mode	Vehicle [27.80%]
Steering Wheel Controls	Steering wheel controls are not fitted. [27.58%]
Digital Audio Receiver Configuration	Remote digital audio receiver not fitted [100%]
Digital Audio Broadcasting Receiver (DAB) Fitment	Not fitted [100%]
Digital Audio Broadcasting Receiver (DAB) Type	Receiver variant 1 fitted. [100%]
DAB	Disabled [100%]
In Band On Channel (IBOC) Receiver Fitment	Fitted
In Band On Channel (IBOC) Receiver Type	Undefined
SDARS Error	No [100%]
Satellite Digital Audio Receiver Fitment	Not fitted [99.99%]
Satellite Digital Audio Receiver Nmi Fitment	Not fitted [99.99%]
SDARS Receiver Type	Undefined [99.99%]
Telstar Telephone Number	8005197474
Vehicle information and Communication System (VICS)	Vehicle information and communication system not fitted. [98.73%]
Traffic Message Channel (TMC) Receiver Fitment	Without traffic message channel. [72.20%]

Safety/Security and Locking

Alarm Fitment	Fitted [100%]
Security Market	Undefined [100%]
BBUS Battery Backed Up Sounder Fitment	Fitted [40.66%]
Alarm Duration by Mode4	No [100%]
Duration of Alarm in Seconds	Undefined [100%]
Vehicle Horn on Alarm Enable	No [100%]
Interior Volumetric Sensor Fitment	Fitted [51.07%]
Number of Alarms per Activation	Undefined [100%]
Number of Alarms per Cycle	Undefined [100%]
Number of Alarms per Parameter Trigger	Undefined [100%]
Number of Triggers per Source	Undefined [100%]
Trun Signal Flash on Anti-Elusion	Disabled [100%]
Turn Signal Flash on Error	Disabled [100%]
Passive Entry	Not fitted [100%]
Remote Start	Not fitted [100%]
Tilt Sensor	Not fitted [81.03%]
CDL Auto Relock	Disable [100%]
CDL First Press Superlock	Enable [99.98%]
CDL Global Close	Disable [100%]
CDL Global Open	Disable [100%]
CDL Key in Based Disarm	Disable [100%]
Speed Related Locking	Enable [67.96%]
CDL Steering Column Lock	Not fitted [100%]
CDL Superlock Chip	Disable [100%]
Superlocking	Disabled [100%]
Door Unlock at Engine Off	Disabled [100%]
Sourced Lazy Close	Inactive [100%]
Entry Delay / Audible Confirm	Entry delay [100%]
Key in Boot - Anti Lock-In Protection	Undefined [100%]
Tail Gate / Boot Lid Power Strike	Not fitted [100%]
Sensorily Ease Tone	Disabled [100%]
Locking Flash Feedback Confirms Latch Status	No [100%]
RF Global Close Permitted	No [100%]
Side Object Detection System	Not fitted [100%]
Driver and Passenger Safety Belt Pretensioners	Undefined [75.32%]
Driver's Inflatable Tubular Structure	Undefined [100%]
Driver's Safety Belt Buckle Switch	Undefined [100%]
Driver's Front Airbag	Undefined [75.32%]
Driver's Knee Airbag	Undefined [100%]
Driver's Rear Head Airbag	Undefined [100%]
Driver's Side Airbag	Undefined [100%]
Passenger Airbag Deactivation Lamp	Undefined [75.32%]
Passenger's Airbag Deactivation Switch	Undefined [100%]
Passenger's Safety Belt Buckle Switch	Undefined [100%]
Passenger's Front Airbag	Undefined [100%]
Passenger's Inflatable Tubular Structure	Undefined [75.32%]
Passenger's Rear Head Airbag	Undefined [100%]
Passenger Occupancy Sensor (OCS) Fitment	Undefined [100%]
Forward Collision Warning	Disabled [100%]
Battery Delivery Mode	Inactive [100%]
Locking Delivery mode	Inactive [100%]
Deployable Battery System	Undefined [100%]

Heating and Ventilation

Hevac System Type	Climate control. [94.33%]
Rear Climatic Control System	Not fitted [96.3%]
Auxiliary Fuel Heating Heater	Fitted [53.13%]
Electric Windshield Defrost	Not fitted [45.02%]
Heated Rear Screen	Fitted [100%]
Heated Seats	Not fitted [46.41%]
Seat Material	Cloth [32.5%]
Temp Sensor	Not fitted [100%]
Front Climatic Seats (Heated and Cooled)	Not fitted [100%]
Rear Climatic Seats (Heated and Cooled)	Not fitted [100%]
Climatic Seats Country	0
Heated Rear Seats	Not fitted [100%]
Park Heater	Not fitted [100%]
PTC	Not fitted [100%]
Climate	Disabled [100%]

Interior & Exterior Lighting

Xenon Head Lights	Not fitted [51.10%]
Auxiliary Driving Lights	Not fitted [100%]
Cornering Lamps Fitment	Not fitted [74.58%]
Strobe Reading Lights	Disabled [92.48%]
Reduced Driveaway	Inactive [98.64%]
Corner Lights Disable	Usable [94.58%]
Corner On Light Threshold	90
Adaptive Front Lighting System	Not fitted [94.58%]
3 Flash Turn Signals	Disabled [96.85%]
North American Specification lights	Not fitted [99.98%]
Police Lamps	Disable [100%]
Exterior Lights Reserved	Not fitted [100%]
Daytime Running Lights	Inactive [100%]
Scandinavian Daytime Running Lights	Disabled [98.23%]
Canadian Daytime Running Lights	Disabled [100%]
Use Reversed Lights for Follow Me Home	Disable [50.98%]
Headlamp Delay	30s [100%]
Fog Lights Operate with Side Lights	Disabled [100%]
Front Fog Lights	Not fitted [100%]
Front Fog Lights Go off with High Beam On	Disabled [100%]
Rear Fog Lights off when Trailer Connected	Disabled [100%]
High Beam Lights	Not fitted [100%]
Lights On when Windshield Wiper On	Disabled [100%]
Side Markers	Not fitted [100%]
Interior Lights On with Tail Gate Ajar	Disabled [100%]
Interior Lights on Approach	Not fitted [100%]
Interior Light Flash Confirm	Usable [100%]
Interior Lights Not Active With Ign in Auxclsory or Off	No [100%]
Interior Lights Off Delay	60
Lights Reserved	Not fitted [100%]

Washers and Wipers

Daytime Run Lamps Wash Strategy	Scandinavian [100%]
Headlamp Wash with Daytime Running Lights	Disabled [100%]
Rain Sensor Sensitivity	Level 1 [100%]
Drip Wipe Feature	Inactive [100%]
Speed Dependent Front Windshield Wipers	Yes [100%]
Headlamp Wash	Not fitted [99.79%]
Speed Dependent Intermittent Windshield Wipers	Yes [100%]
Programmed Wipe	Active [100%]
Rain Sensor	Not fitted [61.23%]
Rear Continuous Wipers	No [100%]
Windshield Wipers up-stroke Wash	Not fitted [100%]

Miscellaneous and Unused

Battery Type	Undefined [100%]
Park Distance Control	Not Fitted [14.68%]
Tyre Pressure Monitoring Display	Disabled [100%]
Passenger's Side Airbag	Undefined [100%]
Configuration File Version	25
Jaguar Safety Belt Reminder	Disabled [100%]
Jaguar Safety Belt Tensioner	Disabled [100%]
Jaguar Safety Belt Reserved	Disabled [100%]
Jaguar Speedometer Calibration Mode4	Market 0 - 3.5% + 2kph [100%]
Jaguar RJPB Offset	+ 0.0kph [100%]
Jaguar Percentage Scaling Factor	0.0% [100%]
Jaguar NAS Safety Belt Sensed	Disabled [100%]
Jaguar Cruise Control	Undefined [100%]
Jaguar Legacy Tyre Size MSB	0
Jaguar Legacy Tyre Size LSB	0
Trim Limited Panic Feature	Not fitted [99.98%]
Phantom Options	Undefined [100%]
Spare Parameter (194)	0
Spare Parameter (195)	0

Filler Bits	0
Filler Bits	0
Filler Bits	0
Filler Bits	0
Filler Bits	0
Filler Bits	0
Filler Bits	0
Filler Bits	0
Filler Bits	0