Replacing the pollen filter on a 2006 Discovery 3 HSE



A replacement pollen filer costs £27.76+VAT, before any discounts.

LR part no. LJKR500020



These two photos are of the new filer. Note that the colour of the paper element.

Don't make the mistake I did and brought a new filter thinking mine was dirty, only to find a new one was exactly the same!



The pollen filter is behind the lower glove box.

Squeeze the supports (top and bottom together) on both sides of the glove box to remove it.



The filer housing is at the top above the fan unit.



Unclip the front cover from the left hand side and remove.



The filer can now be replaced. Take note of the orientation and make sure you insert the new one the correct way around.

Replacing the front cover can be a little tricky.