

Complimentary Visual Health Check

Lancaster Reading

0118 9658400



Customer Information

Name	Mr Ralph Page	Customer Reference	9874116
WIP Number	58318	Next MOT	
Date	16/01/2014	Next Service	or in miles
Registration Number	KX59XBK	Current Mileage	46309
VIN	SALFA2AB5AH162270	Annual Mileage	
Vehicle Details	FREELANDER XS TD4 AUTO		

Manufacturer Recommended

Section	Red	Amber	Green	Recommendation	Authorised
Air Conditioning Service			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Brake Fluid			<input checked="" type="checkbox"/>		<input type="checkbox"/>
MOT/Service Due?			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Pollen Filter			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Timing Belts			<input checked="" type="checkbox"/>		<input type="checkbox"/>

Health Check

Section	Red	Amber	Green	Description	Authorised
Brakes - Front			<input checked="" type="checkbox"/>	FRONT PADS 80% WORN	<input type="checkbox"/>
Brakes - Rear			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Steering/Suspension - Front			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Steering/Suspension - Rear			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Washers/Wipers/Horn			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Lights - Front			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Lights - Rear			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Electrical			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Transmission			<input checked="" type="checkbox"/>	slight bearing noise rear diff req rework to pinion bearing etc	<input type="checkbox"/>
Exhaust			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Interior			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Engine Oil			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Engine			<input checked="" type="checkbox"/>	slight engine oil leak check next service	<input type="checkbox"/>
Cooling System			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Engine Oil - Ltr Top Up			<input checked="" type="checkbox"/>		<input type="checkbox"/>
Misc			<input checked="" type="checkbox"/>	slight vibration @ 1500 to 2000 rpm wheel balance ?	<input type="checkbox"/>

Tyre Report

Tyre Report	Red	Amber	Green	Tyre	Psi	Outer	Middle	Inner	Damaged	Size	Make Fitted	Make Quoted	Authorised
Front Left			<input checked="" type="checkbox"/>	Front Left	5	6	5		<input type="checkbox"/>	235/65r17 108v	Kumho	Kumho	<input type="checkbox"/>
Front Right			<input checked="" type="checkbox"/>	Front Right	5	6	5		<input type="checkbox"/>	235/65r17 108v	Kumho	Goodyear	<input type="checkbox"/>
Rear Right			<input checked="" type="checkbox"/>	Rear Right	7	7	7		<input type="checkbox"/>	235/65r17 108v	Goodyear	Goodyear	<input type="checkbox"/>
Rear Left			<input checked="" type="checkbox"/>	Rear Left	6	7	6		<input type="checkbox"/>	235/65r17 108v	Goodyear	Hankook	<input type="checkbox"/>
Spare			<input checked="" type="checkbox"/>	Spare	7	8	7		<input type="checkbox"/>	235/65r17 108v			<input type="checkbox"/>
Tyre labour			<input checked="" type="checkbox"/>	Tyre labour									<input type="checkbox"/>

Technician

Stephen Barrett

Service Advisor

Vic Bento

Customer Signature

Printed on 16 January 2014 13:20

IMPORTANT This report is the result of a visual inspection only. Further checks or disassembly may be necessary to determine the full extent of requirements